



### CAUTION

Before use, thoroughly read MAXAIR® CAPR® P/N 03521015 User Instruction (received with all CAPR Helmets and available at [www.maxair-systems.com](http://www.maxair-systems.com)).



**REF 2000-201**  
(36/box)

### Intended Use

The MAXAIR 2000-201 Comfort Strips are attached to the front Headband of MAXAIR CAPR Helmet Liners to provide user comfort and to absorb moisture.

### Specifications

#### Material

Polyester

#### Recommended System Temperature Limits

Use/Handling: 0°C to 54°C at a maximum 80% Relative Humidity.

Charging: 0°C to 45°C at a maximum 80% Relative Humidity.

Storage: 0°C to 35°C at a maximum 80% Relative Humidity.

### Regulatory

NIOSH

### Symbol Definitions



Warning, Caution, or Note



Catalog Number



Part Number



### WARNING

Failure to follow User Instructions P/N 03521015 and the instructions contained herein may be hazardous to the user's health.

Use only if package is received unopened and contents are undamaged. If damage is noted, contact the shipper for replacement or repair.

Prior to using any MAXAIR® System or component, be sure to be familiar with the system's NIOSH approved configuration.

DO NOT use if any component is damaged. If any components are damaged or contaminated and therefore unfit for safe and effective use, they should be replaced immediately.

Only trained and experienced personnel who have read and understand the User Instructions should use MAXAIR Products.

The institution using this product in any application is responsible for determining the appropriateness of this equipment relative to regulatory requirements. Bio-Medical Devices Intl, Inc. does not recommend the appropriate systems for a particular institution or facility.

Use only MAXAIR Systems/ NIOSH approved compatible components.

NOT for use in atmospheres immediately dangerous to life or health (IDLH), and atmospheres containing less than 19.5% oxygen, or more than 25% oxygen.

Flammability Level I: fabric may burn if exposed to open flame.

Follow current local regulations governing biohazard waste to safely dispose of single use MAXAIR Products.

If you need more information, contact your BMDI Sales Representative, or call BMDI customer service at 1-800-443-3842.

The Comfort Strips, 2000-201, provide comfort and moisture absorption when placed on the front Headband. They may be changed at user discretion for hygiene purposes.



### NOTE

Only one side of the comfort strip will attach to the hook tape on the Headband.

1. To remove a damaged or soiled Front Comfort Strip, pull it away and off of the Headband.



2. To attach a new Front Comfort Strip, align it parallel to the Headband with the loop side facing the Headband and press it on.

